Terrill Pond Dam-October, 2014





Terrill Pond

- NHFG created pond
- 20 acres
- shallow (max depth 8')

<u>Management</u>

- Trout Pond-4th Saturday in April
- Fly Fishing Only
- Popular spot for local anglers
- Stocked with brook trout from Berlin Hatchery

Dam Safety Deficiencies found in 2009 during a routine inspection

- Dams are typically inspected every 5 years

- Latest scheduled inspection was in 2016



Piping and erosion on right abutment



Eroded crest and exposed cutoff wall

Dam Safety Deficiencies



Displaced stop log bay slab -4"



More Deficiencies





Sinkholes and wet areas on right embankment



Evidence of piping on left embankment



Trees and brush within 15 feet of end of dam Auxiliary spillway overgrown with trees



Red area surpasses 70 F° =Low trout catch rates

Pink area = lowered trout abundance

Water Temperature



Thermal impairment

- Greater than 72F° lethal to juvenile brook trout
- Long exposure times > 75F lethal to all age classes of brook trout

Year	Outlet	Inlet
2014	79.5	66.5
2013	81.3	69.8
2012	81.4*	73.1
2011	81.4**	-
2010	83.7	-

*2012-Aug 4 **2011-Jul 22



- Temperature Model without dam
- Blue indicates favorable water temperatures for trout

Options?

- <u>Repair dam?</u>
 - Seasonal stocked trout fishery
 - Annual dam registration fees, maintenance
 - Historical value

- <u>Remove dam?</u>
 - Improve coldwater
 fisheries habitat and
 restore aquatic
 connectivity
 - Alleviate dam fees and maintenance
 - May alleviate the need to stock trout

NHDES Dam Bureau FY22-23 Capitol Budget

Reconstruction of spillway wall and embankments estimate ~\$600,000

("rough estimate" no design work has been done yet)

No estimate to remove the Dam has been done yet.